



2008 HAWKER 900XP

SERIAL NUMBER HA-0058 | N920PP

ASKING PRICE: MAKE OFFER

TABLE OF CONTENTS

HIGHLIGHTS 3
CABIN EXPERIENCE4
AIRFRAME AND EXTERIOR6
AVIONICS7
ENGINES, APU, AND INSPECTIONS8





HIGHLIGHTS

- Honeywell MSP Gold Level Engine Maintenance Program (Engines and APU)
- Collins Traffic Collision Avoidance System (TCAS II), Change 7.1
- SatcomDirect Flight Deck Freedom package
- WAAS/LPV
- ADS-B
- L5 Avance Gogo Biz L5 4G
- XM Weather

• Low Time

CABIN EXPERIENCE

Midsize

PASSENGERS

9

CABIN HEIGHT

5.75 ft

CABIN WIDTH

6 ft

CABIN LENGTH

21 ft

INTERIOR

Five individual chairs and a three-place divan with a belted lavatory seat for a nine-passenger capability.

Notable Features: Observer's Jump Seat.

All new softgoods and refurbished cabinetry, November 2016.

Neutral beige leather and fabrics and cabinetry finished in a quartered walnut veneer. The cabin seating including the divan is finished in Spinneybeck 4074 beige leather. The lower dado, window reveals and pillows are completed in silver, beiges and greys with Casa Armani fabric pillows. The cabin also features Airshow 4000, microwave, and all the special features of the Hawker Beech 900XP.







AIRFRAME

3,925.9 hours

2,697 landings

MAY 17, 2008

MAINTENANCE TRACKING CAMP

EXTERIOR

Base Color: Ivory White

Stripe Colors: Blue And Teal Accents

Last Painted: Duncan Aviation, October 2016





AVIONICS

- Triple Collins VHF-4000 including AFIS, ACARS and .833 spacing
- Jeppesen Electronic Charts
- · Collins DTU-5000 Data Transfer Unit
- · Pro Line 21 with Four LCD Display System
- Universal CVR-30 Solid State Cockpit Voice Recorder with two-hour recording
- Dual Collins DME-4000 Distance Measuring Equipment
- Collins NAV 4000 ADF/VOR.ILS/GS MBKN
- Collins NAV 4500 VOR.ILS/GS MBKN
- Collins Pro Line 21 w/AFD-3010 & AFD-3010E
- Dual Honeywell FMS-6000 with WAAS/LPV
- Dual Honeywell GPS-4000

- Collins HF-9000 w/SELCAL
- Collins ALT-4000 Radar Altimeter
- AirCell ST-3100 Iridium SatCom
- Honeywell Mark V EGPWS
- Dual Collins TDR-94D Transponders
- Collins TWR-850 w/turbulence
- · Dual cursor control panels
- Dual Monitors for Airshow and DVD System
- ADS-B out
- Aircell L5 Avance Wifi System
- XM Graphical Weather



ENGINES, APU, AND INSPECTIONS

DESCRIPTION TOTAL TIME SINCE NEW: TIME BEFORE OVERHAUL Honeywell 3,913,2 hours TFE731-50R-1H LEFT SERIAL NUMBER TOTAL CYCLES SINCE NEW: PROGRAM COVERAGE: P-122219 2,681 cycles MSP Gold DESCRIPTION TOTAL TIME SINCE NEW: TIME BEFORE OVERHAUL Honeywell 3,913,2 hours RIGHT TFE731-50R-1H TOTAL CYCLES SINCE NEW: SERIAL NUMBER PROGRAM COVERAGE: 2,681 cycles P-122220 MSP Gold

APU	Honeywell GTCP36-150(W)	SERIAL NUMBER P-1063	TIME SINCE NEW: 2,601 hours	program coverage: MSP Gold
-----	----------------------------	----------------------	-----------------------------	-------------------------------

MAJOR INSPECTION STATUS	LAST COMPLETED	NEXT DUE
Inspection B1-B12	FEBRUARY 2022	4592.87 HOURS
Inspection C1-C12	NOVEMBER 2018	4592.87 HOURS
Inspection D1-D12	NOVEMBER 2018	6192.87 HOURS
Inspection E1-E12	JULY 2022	JULY 2023
Inspection F1-F12	OCTOBER 2021	OCTOBER 2023
Inspection G	JUNE 2020	JUNE 2024





